



Award Notice Abstract (Ref No.: 4836022)

Status: Posted

<p>Reference Number: 10775057</p> <p>Control Number: 2024-04-0045</p> <p>Bid Notice Title: Repair and Replacement of Parts of King Long Bus</p> <p>Approved Budget: Php269,860.00</p> <p>Procurement Mode: Negotiated Procurement - Small Value Procurement (Sec. 53.9)</p> <p>Classification: Goods</p> <p>Category: Vehicle Repair and Maintenance</p> <p>Applicable Procurement Rules: Implementing Rules and Regulations</p> <p>Funding Source: Government of the Philippines (GOP)</p> <p>Funding Instrument: Corporate Budget for the Contract Approved by the Board</p> <p>Area of Delivery: Metro Manila</p> <p>Delivery Period: 15 Day/s</p> <p>Contact Person: Romualdo Intia</p> <p>Created By: Romualdo Intia</p>	<p>PHILIPPINE STATE COLLEGE OF AERONAUTICS Piccio Garden, Villamor Airbase, Pasay City Metro Manila, NCR, Philippines</p> <p>Vehicle Repair and Maintenance</p>	<p>Awardee : CARSAN AUTO SERVICE & TRADING CENTER</p> <p>Address : 21 Crisostomo St. Mayamot, Antipolo City Rizal, Region IV-A, Philippines</p> <p>Contact Person : Carlo Llamas Santos</p> <p>Designation : General Manager</p>	<p>Award Type: Award Notice</p> <p>Contract Amount: Php245,000.00</p> <p>Award Date: 09-May-2024</p> <p>Publish Date: 13-May-2024</p> <p>Date Last Updated: 13-May-2024</p> <p>Created By: Romualdo Salud Intia</p> <p>Date Created: 09-May-2024</p> <p>Approver: Romualdo Salud Intia</p> <p>View Documents: 2</p>						
<p>Line Item</p> <table border="1"> <thead> <tr> <th>#</th> <th>Product/Service/Project Name</th> <th>Budget</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>Vehicle Repair and Maintenance, REPAIR AND MAINTENANCE OF SERVICE KINGLONG BUS (PLATE NO. SKE -644) 1 LOT Check Brakes: Remove and Replace Air Dryer Brakes, Front & Rear Steel Tube Hose and Cleaning Brakes 1 LOT General Cleaning Air Condition System Full Down Dashboard, Evaporator, 78181507, 1, Lot</td> <td>Php245,000.00</td> </tr> </tbody> </table>		#	Product/Service/Project Name	Budget	1	Vehicle Repair and Maintenance, REPAIR AND MAINTENANCE OF SERVICE KINGLONG BUS (PLATE NO. SKE -644) 1 LOT Check Brakes: Remove and Replace Air Dryer Brakes, Front & Rear Steel Tube Hose and Cleaning Brakes 1 LOT General Cleaning Air Condition System Full Down Dashboard, Evaporator, 78181507, 1, Lot	Php245,000.00		
#	Product/Service/Project Name	Budget							
1	Vehicle Repair and Maintenance, REPAIR AND MAINTENANCE OF SERVICE KINGLONG BUS (PLATE NO. SKE -644) 1 LOT Check Brakes: Remove and Replace Air Dryer Brakes, Front & Rear Steel Tube Hose and Cleaning Brakes 1 LOT General Cleaning Air Condition System Full Down Dashboard, Evaporator, 78181507, 1, Lot	Php245,000.00							
<p>Reason for Award : Single Bid.</p>									